

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Inspection Report

Permit Number:	C0070021
Inspection Type:	COMPLETE
Inspection Date:	Wednesday, September 07, 2005
Start Date/Time:	9/7/2005 9:00:00 AM
End Date/Time:	9/7/2005 11:00:00 AM
Last Inspection:	Tuesday, August 10, 2004

Inspector: Joe Helfrich, Environmental Scientist III

Weather: <u>cloudy 70 slight breeze</u> InspectionID Report Number: 724

Types of Operations

Accepted by: whedberg 9/28/2005

Permitee: NORTH AMERICAN EQUITIES NV Operator: NORTH AMERICAN EQUITIES NV

Site: BLAZON #1 MINE

Address: CLEARCREEK BOX 555, HELPER UT 84526

Mineral Ownership

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: FORFEITURE

Current Acreages

7.00	Total Permitted		
4.65	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

	-	
☐ Federal		☐ Underground
State		Surface
County		Loadout
_		□

✓ Fee☐ Processing☐ Other☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this site visit was to conduct a complete inspection of the reclaimed Blazon site. There was a potential off-site impact that being the wind-born distribution of thistle to other areas contiguous to the site. The thistle that covered approximately 60% of the reclaimed area has been eliminated.

Inspec	tor's :	Signa	ture
--------	---------	-------	------

Date Thursday, September 15, 2005

Joe Helfrich, Environmental Scientist III Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070021 Inspection Type: COMPLETE

Inspection Date: Wednesday, September 07, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		\checkmark	
2.	Signs and Markers	✓		✓	
3.	Topsoil		✓		
4.a	Hydrologic Balance: Diversions		✓		
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures		~		
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste		✓		
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		✓	
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation	✓		✓	
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.8	a Roads: Construction, Maintenance, Surfacing		✓		
16.	o Roads: Drainage Controls		V		
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		✓		
19.	AVS Check		✓		
20.	Air Quality Permit		✓		
21.	Bonding and Insurance		✓		
22.	Other		✓		

Permit Number: C0070021
Inspection Type: COMPLETE

Inspection Date: Wednesday, September 07, 2005 Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The Blazon mine site underwent bond forfeiture in 1991. There has been no permittee to maintain the site. Reclamation by the state regulatory authority has been discussed since 1994.

2. Signs and Markers

Since the reclamation obligations have been completed by the Division and the use of the property has been returned to the landowner, there are no signs at the point of access to the property.

4.e Hydrologic Balance: Effluent Limitations

Water was flowing at approximately 30 gpm in the reconstructed stream course.

9. Protection of Fish, Wildlife and Related Environmental Issues

Willows are established and doing well along the stream banks.

13. Revegetation

The grasses, forbs, and shrubs are doing well